



REYNOLDA ELECTRIC COMPANY, INC.

Measurements

Sp1	77.1 °F
Sp2	73.9 °F

Parameters

Emissivity	0.9
Refl. temp.	68 °F
Distance	3 ft
Atmospheric temp.	65 °F
Ext. optics temp.	68 °F
Ext. optics trans.	1
Relative humidity	50 %


Geolocation

Compass	29° NE
---------	--------

Note

Panel PA elledge gravity belt sludge switchgear switchgear, check and tighten, load was fine - line side issue of the breaker

2/19/2018 6:34:19 PM




FLIR0015.jpg

FLIR T620

55911055

2/19/2018 6:34:19 PM



FLIR0015.jpg

FLIR T620

55911055

Text annotations

tighten B phase - non critical - temp variance 10deg between line and load